

Atlanta Public Schools/Charter Schools

Turner MS (KIPP Atlanta Collegiate)

Revised

School Assessment Report

March 12, 2021



Table of Contents

Forecasted Sustainment Requirement	110
Forecasted Sustainment Requirement	32
Forecasted Sustainment Requirement	66
Forecasted Sustainment Requirement	92
Condition Index Forecast by Investment Scenario	111
Condition Index Forecast by Investment Scenario	33
Condition Index Forecast by Investment Scenario	67
Condition Index Forecast by Investment Scenario	93
Condition Summary	101
Condition Summary	13
Condition Summary	48
Condition Summary	83
Dashboard Summary	100
Dashboard Summary	12
Dashboard Summary	47
Dashboard Summary	82
Deficiency By Priority Investment	114
Deficiency By Priority Investment	36
Deficiency By Priority Investment	70
Deficiency By Priority Investment	96
Deficiency Details By Priority	116
Deficiency Details By Priority	38
Deficiency Details By Priority	72
Deficiency Details By Priority	98
Deficiency Summary By Category	115
Deficiency Summary By Category	37
Deficiency Summary By Category	71
Deficiency Summary By Category	97
Deficiency Summary By Priority	113

School Assessment Report

Deficiency Summary By Priority	35
Deficiency Summary By Priority	69
Deficiency Summary By Priority	95
Deficiency Summary By System	112
Deficiency Summary By System	34
Deficiency Summary By System	68
Deficiency Summary By System	94
Renewal Schedule	109
Renewal Schedule	29
Renewal Schedule	63
Renewal Schedule	89
System Listing	104
System Listing	16
System Listing	51
System Listing	86
System Notes	105
System Notes	18
System Notes	53
System Notes	88
Condition Detail	103
Condition Detail	15
Condition Detail	50
Condition Detail	85
Executive Summary	11
Executive Summary	46
Executive Summary	81
Executive Summary	99
Glossary	118
Photo Album	102
Photo Album	14
Photo Album	49

School Assessment Report

Photo Album	84
<u>1950_1965 Bldg 501.1</u>	11
<u>1965 Bldg 502.2</u>	46
<u>2020 Bldg</u>	81
<u>Site</u>	99
School Condition Summary	9
School Dashboard Summary	8
School Executive Summary	5

School Executive Summary

The condition of a Campus is the accumulation of the condition evaluations of the component buildings and the site. Building condition is evaluated based on the functional systems and elements of a building and organized according to the **UNIFORMAT II Elemental Classification**. eCOMET uses parametric estimating methodology whereby historical costs for systems, components and equipment are collected by entities such as RSMeans and converted to unit costs, typically \$/SF, and used to approximate future construction costs or replacement values. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Current Replacement Value (CRV)** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	144,380
Year Built:	1950
Last Renovation:	
Replacement Value:	\$28,422,264
Repair Cost:	\$8,842,985
Total FCI:	31.11%
Total RSLI:	51.87%
FCA Score:	68.89



Description:

The KIPP Atlanta Collegiate at Turner MS Facility consists of one main school building with multiple floors and one ancillary single-story building (Gym) located at 98 Anderson Ave., N.W., Atlanta, GA. The original campus was constructed in 1950 and a major renovation completed in 1998. Additions to the main building and the ancillary building were constructed in 1965 and a new cafeteria building completed in 2020.

This report contains condition and adequacy data collected during the 2019 Facility Condition Assessment (FCA) Update. Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building has a basement of cast in-place construction.

B. SUPERSTRUCTURE

School Assessment Report - Turner MS (KIPP Atlanta Collegiate)

Main Building The superstructure is concrete frame. Floor construction is metal pan deck with lightweight fill. Roof construction is precast concrete. The exterior enclosure is comprised of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is a newly installed single-ply PVC application.

GYM Superstructure is concrete frame. Floor construction is slab on-grade. Roof construction is mostly thin shell multi gable concrete structure. The exterior enclosure is comprised of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. The main roof is a built-up application highlighted with a concrete roof center to the buildings design.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with wood or metal frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, lockers, toilet accessories, storage shelving, handrails, fabricated toilet partitions. Stair construction includes steel risers and concrete treads with concrete finishes. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces consist of ceramic tile, carpet, wood, epoxy and vinyl composition tile. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically suspended acoustical tile.

D. SERVICES

CONVEYING: The main building does include a single elevator conveying equipment. Additional conveying equipment also includes a wheelchair lift located at floor level in the gym.

PLUMBING: Plumbing fixtures are typically low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with electric hot water heating. Sanitary waste system is cast iron. Rainwater drainage for the Gym is internal with roof drains.

HVAC: Heating is provided by gas fired boilers. Cooling is supplied by chillers. The heating/cooling distribution system is a ductwork system utilizing air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION: The building does have a fire sprinkler system. The building does have additional fire suppression systems, which include ANSUL kitchen hood protection. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL: The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY: The EST2 Edwards Fire Alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS: This building does not have a separately derived emergency power system. There is no natural gas emergency generator.

E. EQUIPMENT & FURNISHINGS

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, laboratory, vehicle equipment, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flagpole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, propane, natural gas, above ground fuel tanks and site lighting. This site has several areas that are under construction for the new cafeteria effort. Upgrades in these areas are not included in the purview of this report.

CODE REVIEW

ACCESSIBILITY: The building is generally in compliance with applicable ADA requirements with respect to path of travel, interior and exterior doors, interior signage, and toilet room dimensions, fixtures, and fittings. Most building entrances appear to comply with ADA requirements.

LIFE-SAFETY SYSTEMS: The building is not covered with a wet sprinkler system. Fire extinguishers are located throughout the building. Power outlets in wet areas are GFIC protected. The fire alarm system includes detection devices, audio/visual alarms, and pull stations. Emergency/egress lighting is a combination of battery and special circuit systems. Illuminated exit signage is present in corridors and at exit doors. There is no fall protection at the roof.

Attributes:


General Attributes:

Arch Condition Assessor:	Hayden Collins	MEP Condition Assessor:	Hayden Collins
School Grades:	09, 10	DOE Drawing Total GSF:	135080
DOE Facility Number:	0191	Total # of Modular/Portables:	0
DOE Interior Site SF:	135080	Total GSF of Modular/Portables:	0
Approx. Acres:	9.1	Status:	Active


School Dashboard Summary

Gross Area:	144,380	Last Renovation:	
Year Built:	1950	Replacement Value:	\$28,422,264
Repair Cost:	\$8,842,985	RSLI%:	51.87%
FCI:	31.11%		


Deficiency By Category




Deficiency By Priority



Deficiency By System



10 Year Investment Forecast



School Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	73.98%	0.00%	\$0.00
B10 - Superstructure	77.07%	0.00%	\$0.00
B20 - Exterior Enclosure	64.80%	0.00%	\$0.00
B30 - Roofing	100.86%	2.24%	\$14,078.00
C10 - Interior Construction	60.42%	22.31%	\$455,098.00
C20 - Stairs	79.00%	0.00%	\$0.00
C30 - Interior Finishes	69.98%	32.72%	\$813,783.00
D10 - Conveying	0.00%	110.00%	\$165,819.00
D20 - Plumbing	30.48%	65.49%	\$1,038,869.00
D30 - HVAC	32.86%	69.95%	\$2,861,917.00
D40 - Fire Protection	47.51%	0.00%	\$0.00
D50 - Electrical	23.41%	71.07%	\$2,606,474.00
E10 - Equipment	87.80%	0.00%	\$0.00
E20 - Furnishings	19.83%	73.53%	\$221,646.00
G20 - Site Improvements	42.71%	1.59%	\$32,315.84
G30 - Site Mechanical Utilities	58.00%	0.00%	\$0.00
G40 - Site Electrical Utilities	11.23%	68.81%	\$632,985.00
Totals:	51.87%	31.11%	\$8,842,984.84

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Critical Immediate Need	2 - Trending Critical (Year 1)	3 - Necessary (Years 2-5)	4 - Recommended (Years 6-10)	5 - Grandfathered Project triggered
1950_1965 Bldg 501.1	103,864	33.00	\$0.00	\$0.00	\$5,686,969.00	\$0.00	\$0.00
1965 Bldg 502.2	31,216	44.81	\$0.00	\$0.00	\$2,490,715.00	\$0.00	\$0.00
2020 Bldg	9,300	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	135,080	18.67	\$0.00	\$0.00	\$654,630.43	\$10,670.41	\$0.00
Total:		31.11	\$0.00	\$0.00	\$8,832,314.43	\$10,670.41	\$0.00

Deficiencies By Priority



- 1 - Critical Immediate Need
- 2 - Trending Critical (Year 1)
- 3 - Necessary (Years 2-5) - \$8,832,314.43
- 4 - Recommended (Years 6-10) - \$10,670.41
- 5 - Grandfathered Project triggered

Budget Estimate Total: \$8,842,984.84

Executive Summary

The condition of a Campus is the accumulation of the condition evaluations of the component buildings and the site. Building condition is evaluated based on the functional systems and elements of a building and organized according to the **UNIFORMAT II Elemental Classification**. eCOMET uses parametric estimating methodology whereby historical costs for systems, components and equipment are collected by entities such as RSMeans and converted to unit costs, typically \$/SF, and used to approximate future construction costs or replacement values. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Current Replacement Value (CRV)** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Middle Charter
Gross Area (SF):	103,864
Year Built:	1950
Last Renovation:	
Replacement Value:	\$17,231,380
Repair Cost:	\$5,686,969
Total FCI:	33.00%
Total RSLI:	53.20%
FCA Score:	67.00



Description:


The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	Middle Charter	Gross Area:	103,864
Year Built:	1950	Last Renovation:	
Repair Cost:	\$5,686,969	Replacement Value:	\$17,231,380
FCI:	33.00%	RSLI%:	53.20%


Deficiency By Category




Deficiency By Priority



Deficiency By System



10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	79.00%	0.00%	\$0.00
B10 - Superstructure	79.00%	0.00%	\$0.00
B20 - Exterior Enclosure	62.24%	0.00%	\$0.00
B30 - Roofing	100.00%	0.00%	\$0.00
C10 - Interior Construction	69.38%	24.50%	\$302,764.00
C20 - Stairs	79.00%	0.00%	\$0.00
C30 - Interior Finishes	73.57%	30.16%	\$517,554.00
D10 - Conveying	0.00%	110.00%	\$142,813.00
D20 - Plumbing	8.28%	79.64%	\$731,203.00
D30 - HVAC	21.25%	79.75%	\$2,024,516.00
D40 - Fire Protection	41.17%	0.00%	\$0.00
D50 - Electrical	23.73%	74.97%	\$1,746,473.00
E10 - Equipment	78.55%	0.00%	\$0.00
E20 - Furnishings	0.00%	110.00%	\$221,646.00
Totals:	53.20%	33.00%	\$5,686,969.00

Photo Album

The photo album consists of the various cardinal compass directions of the building..

1). Northern Exterior Elevation - Jan 15, 2020



2). Northern Exterior Elevation - Jan 15, 2020



3). Eastern Exterior Elevation - Jan 15, 2020



4). Southern Exterior Elevation - Jan 15, 2020



5). Western Exterior Elevation - Jan 15, 2020



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment)
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system as new construction.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.12	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$635,648
A1030	Slab on Grade	\$6.26	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$650,189
B1010	Floor Construction	\$18.02	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$1,871,629
B1020	Roof Construction	\$12.19	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$1,266,102
B2010	Exterior Walls	\$14.46	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$1,501,873
B2020	Exterior Windows	\$8.66	S.F.	103,864	30	1998	2028		30.00%	0.00%	9			\$899,462
B2030	Exterior Doors	\$0.83	S.F.	103,864	30	2021	2051		106.67%	0.00%	32			\$86,207
B3010120	Single Ply Membrane	\$5.37	S.F.	32,000	15	2019	2034		100.00%	0.00%	15			\$171,840
B3020	Roof Openings	\$0.41	S.F.	32,000	30	2019	2049		100.00%	0.00%	30			\$13,120
C1010	Partitions	\$5.60	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$581,638
C1020	Interior Doors	\$3.65	S.F.	103,864	40	2021	2061		105.00%	0.00%	42			\$379,104
C1030	Fittings	\$2.65	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$302,764.00	\$275,240
C2010	Stair Construction	\$2.85	S.F.	103,864	100	1998	2098		79.00%	0.00%	79			\$296,012
C3010220	Tile	\$9.25	S.F.	2,000	30	2000	2030		36.67%	0.00%	11			\$18,500
C3010230	Paint & Covering	\$1.47	S.F.	102,864	10	2021	2031		120.00%	0.00%	12			\$151,210
C3020420	Ceramic Tile	\$16.74	S.F.	10,000	50	1990	2040		42.00%	0.00%	21			\$167,400
C3020901	Carpet	\$7.50	S.F.	20,000	8	2021	2029		125.00%	0.00%	10			\$150,000
C3020903	VCT	\$3.48	S.F.	70,864	15	2021	2036		113.33%	0.00%	17			\$246,607
C3020999	Other - Wood	\$13.79	S.F.	3,000	50	2021	2071		104.00%	0.00%	52			\$41,370
C3030	Ceiling Finishes	\$9.06	S.F.	51,932	20	2020	2040		105.00%	0.00%	21			\$470,504
C3030	Ceiling Finishes	\$9.06	S.F.	51,932	20	1998	2018		0.00%	110.00%	-1		\$517,554.00	\$470,504
D1010	Elevators and Lifts	\$1.25	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$142,813.00	\$129,830
D2010	Plumbing Fixtures	\$6.40	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$731,203.00	\$664,730
D2020	Domestic Water Distribution	\$0.72	S.F.	103,864	30	1998	2028		30.00%	0.00%	9			\$74,782
D2030	Sanitary Waste	\$1.72	S.F.	103,864	30	1998	2028		30.00%	0.00%	9			\$178,646
D3010	Energy Supply	\$0.61	S.F.	103,864	20	2019	2039		100.00%	0.00%	20			\$63,357
D3020	Heat Generating Systems	\$3.62	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$413,586.00	\$375,988
D3030	Cooling Generating Systems	\$6.11	S.F.	103,864	20	2014	2034		75.00%	0.00%	15			\$634,609
D3040	Distribution Systems	\$10.71	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$1,223,622.00	\$1,112,383
D3050	Terminal & Package Units	\$1.18	S.F.	103,864	15	1998	2013		0.00%	110.00%	-6		\$134,815.00	\$122,560
D3060	Controls & Instrumentation	\$2.21	S.F.	103,864	15	1998	2013		0.00%	110.00%	-6		\$252,493.00	\$229,539
D4010	Sprinklers	\$4.11	S.F.	103,864	30	1998	2028		30.00%	0.00%	9			\$426,881

School Assessment Report - 1950_1965 Bldg 501.1

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D4030	Fire Protection Specialties	\$0.10	S.F.	103,864	15	2013	2028		60.00%	0.00%	9			\$10,386
D4090	Other Fire Protection Systems	\$0.61	S.F.	103,864	15	2021	2036		113.33%	0.00%	17			\$63,357
D5010	Electrical Service/Distribution	\$2.34	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$267,346.00	\$243,042
D5020	Branch Wiring	\$5.36	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$612,382.00	\$556,711
D5020	Lighting	\$6.57	S.F.	51,932	20	1998	2018		0.00%	100.00%	-1		\$341,193.00	\$341,193
D5020	Lighting (1)	\$6.57	S.F.	51,932	20	2021	2041		110.00%	0.00%	22			\$341,193
D5030810	Security & Detection Systems	\$1.51	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$172,518.00	\$156,835
D5030910	Fire Alarm Systems	\$2.74	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$313,046.00	\$284,587
D5030920	Data Communication	\$3.56	S.F.	103,864	25	2006	2031		48.00%	0.00%	12			\$369,756
D5090	Other Electrical Systems	\$0.35	S.F.	103,864	15			2019	0.00%	110.00%	0		\$39,988.00	\$36,352
E1020	Institutional Equipment	\$1.81	S.F.	103,864	20	2012	2032		65.00%	0.00%	13			\$187,994
E1090	Other Equipment	\$0.78	S.F.	103,864	20	2021	2041		110.00%	0.00%	22			\$81,014
E2010	Fixed Furnishings	\$1.94	S.F.	103,864	20	1998	2018		0.00%	110.00%	-1		\$221,646.00	\$201,496
Total									53.20%	33.00%			\$5,686,969.00	\$17,231,380

System Notes

The facility description in the executive summary contains an overview of each system. The system notes listed below provide additional information on select systems found within the facility.

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: B3010 - Roof Coverings



Note:

School Assessment Report - 1950_1965 Bldg 501.1

System: B3010120 - Single Ply Membrane




Note:

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.



School Assessment Report - 1950_1965 Bldg 501.1

System: C1030 - Fittings



Note:

System: C2010 - Stair Construction



Note:

System: C3010220 - Tile



Note:

System: C3010230 - Paint & Covering

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

School Assessment Report - 1950_1965 Bldg 501.1

System: C3020420 - Ceramic Tile



Note:

System: C3020901 - Carpet

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: C3020903 - VCT

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: C3020999 - Other - Wood

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: C3030 - Ceiling Finishes



Note:

System: C3030 - Ceiling Finishes

This system contains no images

Note: The systems has been updated in common areas. This is based on the information provided by APS of recent renovations, repairs or replacement projects.


School Assessment Report - 1950_1965 Bldg 501.1

System: D1010 - Elevators and Lifts



Note:

System: D2010 - Plumbing Fixtures



Note:



System: D2020 - Domestic Water Distribution



Note:

School Assessment Report - 1950_1965 Bldg 501.1

System: D2030 - Sanitary Waste



Note:

System: D3010 - Energy Supply



Note:

System: D3020 - Heat Generating Systems



Note:

School Assessment Report - 1950_1965 Bldg 501.1

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:


School Assessment Report - 1950_1965 Bldg 501.1

System: D3060 - Controls & Instrumentation



Note:

System: D4010 - Sprinklers



Note:

System: D4090 - Other Fire Protection Systems

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: D5010 - Electrical Service/Distribution



Note:


School Assessment Report - 1950_1965 Bldg 501.1

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5020 - Lighting (1)

This system contains no images

Note: The systems has been updated in common areas. This is based on the information provided by APS of recent renovations, repairs or replacement projects.

System: D5030810 - Security & Detection Systems



Note:

School Assessment Report - 1950_1965 Bldg 501.1

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the System Listing table. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
Total:	\$5,686,969	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,282,274	\$221,746	\$8,190,989
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,290,953	\$0	\$1,290,953
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$302,764	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$302,764
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1950_1965 Bldg 501.1

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
C3010220 - Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020420 - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020901 - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$221,746	\$221,746
C3020903 - VCT	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020999 - Other - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$517,554	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$517,554
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$142,813	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$142,813
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$731,203	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$731,203
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$107,331	\$0	\$107,331
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$256,402	\$0	\$256,402
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3010 - Energy Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$413,586	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$413,586
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$1,223,622	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,223,622
D3050 - Terminal & Package Units	\$134,815	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$134,815
D3060 - Controls & Instrumentation	\$252,493	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$252,493
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$612,681	\$0	\$612,681
D4030 - Fire Protection Specialties	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,907	\$0	\$14,907
D4090 - Other Fire Protection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$267,346	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$267,346
D5020 - Branch Wiring	\$612,382	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$612,382
D5020 - Lighting	\$341,193	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$341,193
D5020 - Lighting (1)	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1950_1965 Bldg 501.1

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
D5030810 - Security & Detection Systems	\$172,518	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$172,518
D5030910 - Fire Alarm Systems	\$313,046	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$313,046
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems	\$39,988	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,988
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$221,646	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$221,646

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasted capital renewal (sustainment) requirements over the next ten years.




Condition Index Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 33%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2020	\$0	\$354,966.00	31.00%	\$709,933.00	29.00%
2021	\$0	\$365,615.00	29.00%	\$731,231.00	25.00%
2022	\$0	\$376,584.00	27.00%	\$753,168.00	21.00%
2023	\$0	\$387,881.00	25.00%	\$775,763.00	17.00%
2024	\$0	\$399,518.00	23.00%	\$799,036.00	13.00%
2025	\$0	\$411,503.00	21.00%	\$823,007.00	9.00%
2026	\$0	\$423,848.00	19.00%	\$847,697.00	5.00%
2027	\$0	\$436,564.00	17.00%	\$873,128.00	1.00%
2028	\$2,282,274	\$449,661.00	25.15%	\$899,322.00	7.15%
2029	\$221,746	\$463,151.00	24.11%	\$926,301.00	4.11%
Total:	\$2,504,020	\$4,069,291.00		\$8,138,586.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$5,686,969.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$5,686,969.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Critical Immediate Need	2 - Trending Critical (Year 1)	3 - Necessary (Years 2-5)	4 - Recommended (Years 6-10)	5 - Grandfathered Project triggered	Total
C1030	Fittings	\$0.00	\$0.00	\$302,764.00	\$0.00	\$0.00	\$302,764.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$517,554.00	\$0.00	\$0.00	\$517,554.00
D1010	Elevators and Lifts	\$0.00	\$0.00	\$142,813.00	\$0.00	\$0.00	\$142,813.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$731,203.00	\$0.00	\$0.00	\$731,203.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$413,586.00	\$0.00	\$0.00	\$413,586.00
D3040	Distribution Systems	\$0.00	\$0.00	\$1,223,622.00	\$0.00	\$0.00	\$1,223,622.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$134,815.00	\$0.00	\$0.00	\$134,815.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$252,493.00	\$0.00	\$0.00	\$252,493.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$267,346.00	\$0.00	\$0.00	\$267,346.00
D5020	Branch Wiring	\$0.00	\$0.00	\$612,382.00	\$0.00	\$0.00	\$612,382.00
D5020	Lighting	\$0.00	\$0.00	\$341,193.00	\$0.00	\$0.00	\$341,193.00
D5030810	Security & Detection Systems	\$0.00	\$0.00	\$172,518.00	\$0.00	\$0.00	\$172,518.00
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$313,046.00	\$0.00	\$0.00	\$313,046.00
D5090	Other Electrical Systems	\$0.00	\$0.00	\$39,988.00	\$0.00	\$0.00	\$39,988.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$221,646.00	\$0.00	\$0.00	\$221,646.00
	Total:	\$0.00	\$0.00	\$5,686,969.00	\$0.00	\$0.00	\$5,686,969.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary (Years 2-5):

System: C1030 - Fittings



Location: Throughout building
Distress: Beyond Expected Life
Category: ADA Compliance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$302,764.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: Fittings, such as toilet partitions, lockers, signage and railing, are beyond their expected service life, worn and damaged in areas, and should be replaced and upgraded for compliance with ADA standards.

System: C3030 - Ceiling Finishes



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 51,932.00
Unit of Measure: S.F.
Estimate: \$517,554.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: The acoustical ceiling tile finish in classrooms is beyond its expected service life and is recommended for replacement in conjunction with other recommended renovations.

System: D1010 - Elevators and Lifts



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$142,813.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: The ADA elevator system is from a late 1990's installation. The elevator system has exceeded its life cycle and recommended for upgrade. All aspects of the current ADA standards are expected to be included in the new installation.

System: D2010 - Plumbing Fixtures



Location: Restroom
Distress: Beyond Expected Life
Category: ADA Compliance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$731,203.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: The plumbing fixtures are from original construction with few exceptions. The system is beyond its expected life cycle and upgrades are warranted for ADA compliance.

System: D3020 - Heat Generating Systems



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$413,586.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: The heat generation for this school is nearing the end of its useful life. The piping, fitting or auxiliary equipment as well as the main boiler system is recommended for upgrade. This deficiency provides a budgetary consideration for upgrades to support the heat generation system.

System: D3040 - Distribution Systems



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$1,223,622.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: The distribution system is beyond its expected service life and should be scheduled for replacement.

System: D3050 - Terminal & Package Units



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$134,815.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

The terminal and package units are nearing the end of their useful life. The system is functional however upgrades are warranted.

System: D3060 - Controls & Instrumentation



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$252,493.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

The heating generation systems, exhaust and ventilation systems, energy monitoring and controls as well as the building automation systems are original. Several issues have surfaced over recent years and isolated upgrades have taken place to support the systems. This deficiency provides a budgetary consideration for a universal upgrade.

System: D5010 - Electrical Service/Distribution



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$267,346.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes: The electrical service and distribution system consist of a service disconnect, primary main rated at 2000 amps, breaker system, switch box, and conduit and wiring to equipment, interior and exterior lights. This system is a mix of the old and new. Some of the system was recently upgraded; however, a majority of the system is original. Upgrades are warranted.

System: D5020 - Branch Wiring



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$612,382.00
Assessor Name: Eduardo Lopez
Date Created: 01/20/2020

Notes: The electrical distribution system is aged and should be replaced and upgraded for compliance with current code requirements.

System: D5020 - Lighting



Location: Classroom Area
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 51,932.00
Unit of Measure: S.F.
Estimate: \$341,193.00
Assessor Name: Eduardo Lopez
Date Created: 03/11/2021

Notes: The original lighting and branch wiring in the classrooms is operational but is aged and should be replaced with an energy efficient system.

System: D5030810 - Security & Detection Systems



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$172,518.00
Assessor Name: Eduardo Lopez
Date Created: 01/20/2020

Notes: The security detection and alarm system is nearing the end of its expected life and upgrades are warranted. This deficiency provides a budgetary consideration for universal upgrades and should be replaced in conjunction with other recommended renovations.

System: D5030910 - Fire Alarm Systems



Location: Throughout Building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$313,046.00
Assessor Name: Eduardo Lopez
Date Created: 03/11/2021

Notes: The Edwards Fire Control Instruments system Multi-zone unit with detection, push stations, lights, and warning sounds. This system is nearing the end of its expected life and upgrades are warranted. This deficiency provides a budgetary consideration for universal upgrades to the fire alarm system.

System: D5090 - Other Electrical Systems

This deficiency has no image.

Location: Throughout building
Distress: Missing
Category: Reliability
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 103,864.00
Unit of Measure: S.F.
Estimate: \$39,988.00
Assessor Name: Eduardo Lopez
Date Created: 10/23/2014

Notes: No emergency generator, install per client standard.



Date Created: 09/30/2019

Page 45 of 122

Executive Summary

The condition of a Campus is the accumulation of the condition evaluations of the component buildings and the site. Building condition is evaluated based on the functional systems and elements of a building and organized according to the **UNIFORMAT II Elemental Classification**. eCOMET uses parametric estimating methodology whereby historical costs for systems, components and equipment are collected by entities such as RSMeans and converted to unit costs, typically \$/SF, and used to approximate future construction costs or replacement values. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Current Replacement Value (CRV)** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Middle Charter
Gross Area (SF):	31,216
Year Built:	1965
Last Renovation:	
Replacement Value:	\$5,558,350
Repair Cost:	\$2,490,715
Total FCI:	44.81%
Total RSLI:	37.69%
FCA Score:	55.19



Description:


The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	Middle Charter	Gross Area:	31,216
Year Built:	1965	Last Renovation:	
Repair Cost:	\$2,490,715	Replacement Value:	\$5,558,350
FCI:	44.81%	RSLI%:	37.69%


Deficiency By Category




Deficiency By Priority



Deficiency By System



10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	46.00%	0.00%	\$0.00
B10 - Superstructure	46.00%	0.00%	\$0.00
B20 - Exterior Enclosure	59.36%	0.00%	\$0.00
B30 - Roofing	100.28%	3.76%	\$14,078.00
C10 - Interior Construction	35.71%	22.67%	\$152,334.00
C30 - Interior Finishes	39.51%	58.74%	\$296,229.00
D10 - Conveying	0.00%	110.00%	\$23,006.00
D20 - Plumbing	52.68%	54.82%	\$307,666.00
D30 - HVAC	26.85%	78.70%	\$837,401.00
D40 - Fire Protection	60.00%	0.00%	\$0.00
D50 - Electrical	5.43%	77.91%	\$860,001.00
E20 - Furnishings	30.00%	0.00%	\$0.00
Totals:	37.69%	44.81%	\$2,490,715.00

Photo Album

The photo album consists of the various cardinal compass directions of the building..

1). Northern Exterior Elevation - Jan 15, 2020



2). Eastern Exterior Elevation - Jan 15, 2020



3). Southern Exterior Elevation - Jan 15, 2020



4). Western Exterior Elevation - Jan 15, 2020



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment)
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system as new construction.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

School Assessment Report - 1965 Bldg 502.2

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$11.94	S.F.	31,216	100	1965	2065		46.00%	0.00%	46			\$372,719
B1020	Roof Construction	\$9.68	S.F.	31,216	100	1965	2065		46.00%	0.00%	46			\$302,171
B2010	Exterior Walls	\$12.25	S.F.	31,216	100	1965	2065		46.00%	0.00%	46			\$382,396
B2020	Exterior Windows	\$0.67	S.F.	31,216	30	2003	2033		46.67%	0.00%	14			\$20,915
B2030	Exterior Doors	\$3.64	S.F.	31,216	30	2021	2051		106.67%	0.00%	32			\$113,626
B3010105	Built-Up	\$7.15	S.F.	11,000	25	2021	2046		108.00%	0.00%	27			\$78,650
B3010999	Other - Concrete	\$13.99	S.F.	20,216	75	2021	2096		102.67%	0.00%	77			\$282,822
B3020	Roof Openings	\$0.41	S.F.	31,216	20	1965	1985		0.00%	109.99%	-34		\$14,078.00	\$12,799
C1010	Partitions	\$14.66	S.F.	31,216	100	1965	2065		46.00%	0.00%	46			\$457,627
C1020	Interior Doors	\$1.99	S.F.	31,216	40	1998	2038		47.50%	0.00%	19			\$62,120
C1030	Fittings	\$4.88	S.F.	31,216	20	1965	1985		0.00%	100.00%	-34		\$152,334.00	\$152,334
C3010230	Paint & Covering	\$1.58	S.F.	10,000	10	1965	1975		0.00%	0.00%	-44			\$15,800
C3020405	Epoxy	\$17.30	S.F.	3,000	15	2015	2030		73.33%	0.00%	11			\$51,900
C3020420	Ceramic Tile	\$16.74	S.F.	2,000	50	1965	2015		0.00%	150.00%	-4		\$50,220.00	\$33,480
C3020901	Carpet	\$7.50	S.F.	2,000	8	2014	2022		37.50%	0.00%	3			\$15,000
C3020903	VCT	\$3.48	S.F.	12,216	15	1965	1980		0.00%	155.00%	-39		\$65,893.00	\$42,512
C3020999	Other - Wood	\$13.79	S.F.	12,000	50	2016	2066		94.00%	0.00%	47			\$165,480
C3030	Ceiling Finishes	\$5.77	S.F.	31,216	20	1965	1985		0.00%	100.00%	-34		\$180,116.00	\$180,116
D1010	Elevators and Lifts	\$0.67	S.F.	31,216	20	2003	2023	2019	0.00%	110.00%	0		\$23,006.00	\$20,915
D2010	Plumbing Fixtures	\$9.02	S.F.	31,216	20	2020	2040		105.00%	0.00%	21			\$281,568
D2020	Domestic Water Distribution	\$4.46	S.F.	31,216	30	1965	1995		0.00%	110.00%	-24		\$153,146.00	\$139,223
D2030	Sanitary Waste	\$3.18	S.F.	31,216	30	1965	1995		0.00%	110.00%	-24		\$109,194.00	\$99,267
D2040	Rain Water Drainage	\$1.32	S.F.	31,216	20	1965	1985		0.00%	110.00%	-34		\$45,326.00	\$41,205
D3010	Energy Supply	\$0.61	S.F.	31,216	50	1998	2048		58.00%	0.00%	29			\$19,042
D3020	Heat Generating Systems	\$3.14	S.F.	31,216	20	1998	2018		0.00%	110.00%	-1		\$107,820.00	\$98,018
D3030	Cooling Generating Systems	\$8.80	S.F.	31,216	20	2019	2039		100.00%	0.00%	20			\$274,701
D3040	Distribution Systems	\$17.16	S.F.	31,216	20	1990	2010		0.00%	110.00%	-9		\$589,233.00	\$535,667
D3050	Terminal & Package Units	\$0.12	S.F.	311,216	15	1998	2013		0.00%	110.00%	-6		\$41,081.00	\$37,346
D3060	Controls & Instrumentation	\$3.18	S.F.	31,216	15	1994	2009		0.00%	100.00%	-10		\$99,267.00	\$99,267
D4030	Fire Protection Specialties	\$0.18	S.F.	31,216	15	2013	2028		60.00%	0.00%	9			\$5,619
D5010	Electrical Service/Distribution	\$5.63	S.F.	31,216	20	1980	2000		0.00%	100.00%	-19		\$175,746.00	\$175,746
D5020	Branch Wiring	\$7.74	S.F.	31,216	20	1980	2000		0.00%	100.00%	-19		\$241,612.00	\$241,612
D5020	Lighting	\$12.33	S.F.	31,216	20	1980	2000		0.00%	100.00%	-19		\$384,893.00	\$384,893
D5030810	Security & Detection Systems	\$1.51	S.F.	31,216	20	2000	2020		5.00%	0.00%	1			\$47,136
D5030910	Fire Alarm Systems	\$2.74	S.F.	31,216	20	2000	2020		5.00%	0.00%	1			\$85,532
D5030920	Data Communication	\$3.56	S.F.	31,216	25	2006	2031		48.00%	0.00%	12			\$111,129
D5090	Other Electrical Systems	\$1.85	S.F.	31,216	15			2013	0.00%	100.00%	-6		\$57,750.00	\$57,750
E2010	Fixed Furnishings	\$1.93	S.F.	31,216	20	1965	1985	2025	30.00%	0.00%	6			\$60,247
Total									37.69%	44.81%			\$2,490,715.00	\$5,558,350

System Notes

The facility description in the executive summary contains an overview of each system. The system notes listed below provide additional information on select systems found within the facility.

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: B3010105 - Built-Up

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

System: B3010999 - Other - Concrete

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.



School Assessment Report - 1965 Bldg 502.2

System: B3020 - Roof Openings




Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:


School Assessment Report - 1965 Bldg 502.2

System: C1030 - Fittings



Note:

System: C3010230 - Paint & Covering



Note:

System: C3020405 - Epoxy



Note:


School Assessment Report - 1965 Bldg 502.2

System: C3020420 - Ceramic Tile



Note:

System: C3020901 - Carpet



Note:

System: C3020903 - VCT



Note:

School Assessment Report - 1965 Bldg 502.2

System: C3020999 - Other - Wood



Note:

System: C3030 - Ceiling Finishes



Note:

System: D1010 - Elevators and Lifts



Note:

System: D2010 - Plumbing Fixtures

This system contains no images

Note: The systems has been updated based on the information provided by APS of recent renovations, repairs or replacement projects.

School Assessment Report - 1965 Bldg 502.2

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

School Assessment Report - 1965 Bldg 502.2

System: D3010 - Energy Supply



Note:

System: D3020 - Heat Generating Systems



Note:

System: D3030 - Cooling Generating Systems



Note:

School Assessment Report - 1965 Bldg 502.2

System: D3040 - Distribution Systems




Note:

System: D3060 - Controls & Instrumentation



Note:


System: D4030 - Fire Protection Specialties



Note:



School Assessment Report - 1965 Bldg 502.2

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5030 - Communications and Security



Note:

School Assessment Report - 1965 Bldg 502.2

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the System Listing table. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
Total:	\$2,490,715	\$150,313	\$0	\$18,030	\$0	\$0	\$79,132	\$0	\$0	\$82,682	\$23,357	\$2,844,230
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010999 - Other - Concrete	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$14,078	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,078
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$152,334	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$152,334
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,357	\$23,357
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020405 - Epoxy	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1965 Bldg 502.2

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
C3020420 - Ceramic Tile	\$50,220	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$50,220
C3020901 - Carpet	\$0	\$0	\$0	\$18,030	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,030
C3020903 - VCT	\$65,893	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,893
C3020999 - Other - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$180,116	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$180,116
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$23,006	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,006
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$153,146	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$153,146
D2030 - Sanitary Waste	\$109,194	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$109,194
D2040 - Rain Water Drainage	\$45,326	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$45,326
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3010 - Energy Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$107,820	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$107,820
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$589,233	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$589,233
D3050 - Terminal & Package Units	\$41,081	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,081
D3060 - Controls & Instrumentation	\$99,267	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$99,267
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4030 - Fire Protection Specialties	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,332	\$0	\$7,332
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$175,746	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$175,746
D5020 - Branch Wiring	\$241,612	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$241,612
D5020 - Lighting	\$384,893	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$384,893
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$53,406	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$53,406
D5030910 - Fire Alarm Systems	\$0	\$96,908	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$96,908
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems	\$57,750	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$75,351	\$0	\$133,101
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1965 Bldg 502.2

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$79,132	\$0	\$0	\$0	\$0	\$79,132

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasted capital renewal (sustainment) requirements over the next ten years.




Condition Index Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 44.81%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2020	\$150,313	\$114,502.00	45.44%	\$229,004.00	43.44%
2021	\$0	\$117,937.00	43.44%	\$235,874.00	39.44%
2022	\$18,030	\$121,475.00	41.73%	\$242,950.00	35.73%
2023	\$0	\$125,119.00	39.73%	\$250,239.00	31.73%
2024	\$0	\$128,873.00	37.73%	\$257,746.00	27.73%
2025	\$79,132	\$132,739.00	36.92%	\$265,478.00	24.92%
2026	\$0	\$136,721.00	34.92%	\$273,443.00	20.92%
2027	\$0	\$140,823.00	32.92%	\$281,646.00	16.92%
2028	\$7,332	\$145,048.00	31.03%	\$290,095.00	13.03%
2029	\$23,357	\$149,399.00	29.34%	\$298,798.00	9.34%
Total:	\$278,164	\$1,312,636.00		\$2,625,273.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$2,490,715.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$2,490,715.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Critical Immediate Need	2 - Trending Critical (Year 1)	3 - Necessary (Years 2-5)	4 - Recommended (Years 6-10)	5 - Grandfathered Project triggered	Total
B3020	Roof Openings	\$0.00	\$0.00	\$14,078.00	\$0.00	\$0.00	\$14,078.00
C1030	Fittings	\$0.00	\$0.00	\$152,334.00	\$0.00	\$0.00	\$152,334.00
C3020420	Ceramic Tile	\$0.00	\$0.00	\$50,220.00	\$0.00	\$0.00	\$50,220.00
C3020903	VCT	\$0.00	\$0.00	\$65,893.00	\$0.00	\$0.00	\$65,893.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$180,116.00	\$0.00	\$0.00	\$180,116.00
D1010	Elevators and Lifts	\$0.00	\$0.00	\$23,006.00	\$0.00	\$0.00	\$23,006.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$153,146.00	\$0.00	\$0.00	\$153,146.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$109,194.00	\$0.00	\$0.00	\$109,194.00
D2040	Rain Water Drainage	\$0.00	\$0.00	\$45,326.00	\$0.00	\$0.00	\$45,326.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$107,820.00	\$0.00	\$0.00	\$107,820.00
D3040	Distribution Systems	\$0.00	\$0.00	\$589,233.00	\$0.00	\$0.00	\$589,233.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$41,081.00	\$0.00	\$0.00	\$41,081.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$99,267.00	\$0.00	\$0.00	\$99,267.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$175,746.00	\$0.00	\$0.00	\$175,746.00
D5020	Branch Wiring	\$0.00	\$0.00	\$241,612.00	\$0.00	\$0.00	\$241,612.00
D5020	Lighting	\$0.00	\$0.00	\$384,893.00	\$0.00	\$0.00	\$384,893.00
D5090	Other Electrical Systems	\$0.00	\$0.00	\$57,750.00	\$0.00	\$0.00	\$57,750.00
	Total:	\$0.00	\$0.00	\$2,490,715.00	\$0.00	\$0.00	\$2,490,715.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary (Years 2-5):

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$14,078.00
Assessor Name: Eduardo Lopez
Date Created: 01/20/2020

Notes: Roof openings are beyond their expected life and should be scheduled for replacement in conjunction with the roof covering.

System: C1030 - Fittings



Location: Throughout building
Distress: Beyond Expected Life
Category: ADA Compliance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$152,334.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

Fittings, such as toilet partitions, lockers, signage and railing, are beyond their expected service life, worn and damaged in areas, and should be replaced and upgraded for compliance with ADA standards.

System: C3020420 - Ceramic Tile



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 2,000.00
Unit of Measure: S.F.
Estimate: \$50,220.00
Assessor Name: Eduardo Lopez
Date Created: 01/20/2020

Notes: The ceramic tile floor finish is beyond its expected service life and should be replaced in conjunction with other recommended renovations.

System: C3020903 - VCT



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 12,216.00
Unit of Measure: S.F.
Estimate: \$65,893.00
Assessor Name: Eduardo Lopez
Date Created: 01/20/2020

Notes: The VCT floor finish is beyond its expected service life, worn and damaged, and is recommended for replacement.

System: C3030 - Ceiling Finishes



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$180,116.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

The acoustical ceiling tile finish is beyond its expected service life and is recommended for replacement in conjunction with other recommended renovations.

System: D1010 - Elevators and Lifts



Location: Gym
Distress: Beyond Expected Life
Category: ADA Compliance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$23,006.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

The ADA elevator system has exceeded its life cycle and recommended for upgrade. All aspects of the current ADA standards are expected to be included in the new installation.

System: D2020 - Domestic Water Distribution



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$153,146.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes: The domestic water distribution system consists of galvanized and copper pipes, valves and domestic water supply. The system is beyond its expected life cycle and upgrades are recommended.

System: D2030 - Sanitary Waste



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$109,194.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes: The sanitary waste system is original and beyond its expected life cycle. Upgrades to the existing system are considered necessary.

System: D2040 - Rain Water Drainage



Location: Roof
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$45,326.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes: The roof drains, insulation and fittings that support the water run off from this roof are original. The insulation is damaged from leaks and the drains have developed leaks. This deficiency provides a budgetary consideration for a new rainwater drainage system. This is expected to be completed as part of an overall effort to upgrade the roof and should be completed as part of the recommended roof upgrade also in this report.

System: D3020 - Heat Generating Systems

This deficiency has no image.

Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$107,820.00
Assessor Name: Eduardo Lopez
Date Created: 09/30/2019

Notes:

The heat generation for this school is nearing the end of its useful life. The piping, fitting or auxiliary equipment as well as the main boiler system is recommended for upgrade. This deficiency provides a budgetary consideration for upgrades to support the heat generation system.

System: D3040 - Distribution Systems



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$589,233.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

The distribution system is beyond its expected service life and should be scheduled for replacement.

System: D3050 - Terminal & Package Units

This deficiency has no image.

Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 311,216.00
Unit of Measure: S.F.
Estimate: \$41,081.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

Terminal and Package Unit is not working and is beyond expected life and should be replaced.

System: D3060 - Controls & Instrumentation



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$99,267.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes:

KIPP Academy has installed a few local HVAC controllers for some of the main HVAC units. However there is no overall BAS or other type of central control for the HVAC systems.

System: D5010 - Electrical Service/Distribution



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$175,746.00
Assessor Name: Eduardo Lopez
Date Created: 10/22/2014

Notes:

The electrical service and distribution system consist of a service disconnect, primary main rated at 2000 amps, breaker system, switch box, and conduit and wiring to equipment, interior and exterior lights. This system is a mix of the old and new. Some of the system was recently upgraded; however, a majority of the system is original. Upgrades are warranted.

System: D5020 - Branch Wiring



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$241,612.00
Assessor Name: Eduardo Lopez
Date Created: 01/20/2020

Notes: The electrical distribution system is aged and should be replaced and upgraded for compliance with current code requirements.

System: D5020 - Lighting



Location: Throughout building
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 31,216.00
Unit of Measure: S.F.
Estimate: \$384,893.00
Assessor Name: Eduardo Lopez
Date Created: 02/22/2020

Notes: The original lighting and branch wiring system is operational but is aged and should be replaced with an energy efficient system.

System: D5090 - Other Electrical Systems

This deficiency has no image.

Location: Throughout building

Distress: Missing

Category: Reliability

Priority: 3 - Necessary (Years 2-5)

Correction: Renew System

Qty: 31,216.00

Unit of Measure: S.F.

Estimate: \$57,750.00

Assessor Name: Eduardo Lopez

Date Created: 10/30/2014

Notes: No emergency generator, install per client standard

Executive Summary

The condition of a Campus is the accumulation of the condition evaluations of the component buildings and the site. Building condition is evaluated based on the functional systems and elements of a building and organized according to the **UNIFORMAT II Elemental Classification**. eCOMET uses parametric estimating methodology whereby historical costs for systems, components and equipment are collected by entities such as RSMeans and converted to unit costs, typically \$/SF, and used to approximate future construction costs or replacement values. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Current Replacement Value (CRV)** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:

Gross Area (SF): 9,300

Year Built: 2020

Last Renovation:

Replacement Value: \$2,069,125

Repair Cost: \$0

Total FCI: 0.00%

Total RSLI: 104.12%

FCA Score: 100.00

Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:		Gross Area:	9,300
Year Built:	2020	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$2,069,125
FCI:	0.00%	RSLI%:	104.12%

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	101.00%	0.00%	\$0.00
B10 - Superstructure	101.00%	0.00%	\$0.00
B20 - Exterior Enclosure	101.95%	0.00%	\$0.00
B30 - Roofing	106.38%	0.00%	\$0.00
C10 - Interior Construction	102.36%	0.00%	\$0.00
C30 - Interior Finishes	104.49%	0.00%	\$0.00
D20 - Plumbing	104.56%	0.00%	\$0.00
D30 - HVAC	106.21%	0.00%	\$0.00
D40 - Fire Protection	103.81%	0.00%	\$0.00
D50 - Electrical	105.00%	0.00%	\$0.00
E10 - Equipment	105.00%	0.00%	\$0.00
E20 - Furnishings	105.00%	0.00%	\$0.00
Totals:	104.12%	0.00%	\$0.00

Photo Album

The photo album consists of the various cardinal compass directions of the building..

No data found for this asset

Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment)
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system as new construction.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

School Assessment Report - 2020 Bldg

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$7.89	S.F.	9,300	100	2020	2120		101.00%	0.00%	101			\$73,377
A1030	Slab on Grade	\$7.89	S.F.	9,300	100	2020	2120		101.00%	0.00%	101			\$73,377
B1020	Roof Construction	\$14.93	S.F.	9,300	100	2020	2120		101.00%	0.00%	101			\$138,849
B2010	Exterior Walls	\$15.78	S.F.	9,300	100	2020	2120		101.00%	0.00%	101			\$146,754
B2020	Exterior Windows	\$9.85	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$91,605
B2030	Exterior Doors	\$0.96	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$8,928
B3010120	Single Ply Membrane	\$6.70	S.F.	9,300	15	2020	2035		106.67%	0.00%	16			\$62,310
B3020	Roof Openings	\$0.63	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$5,859
C1010	Partitions	\$6.66	S.F.	9,300	100	2020	2120		101.00%	0.00%	101			\$61,938
C1020	Interior Doors	\$4.36	S.F.	9,300	40	2020	2060		102.50%	0.00%	41			\$40,548
C1030	Fittings	\$3.18	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$29,574
C3010230	Paint & Covering	\$1.84	S.F.	5,300	10	2020	2030		110.00%	0.00%	11			\$9,752
C3010901	Wainscot - FRP	\$5.91	S.F.	4,000	10	2020	2030		110.00%	0.00%	11			\$23,640
C3020420	Ceramic Tile	\$20.89	S.F.	5,300	50	2020	2070		102.00%	0.00%	51			\$110,717
C3020903	VCT	\$4.35	S.F.	4,000	15	2020	2035		106.67%	0.00%	16			\$17,400
C3030	Ceiling Finishes	\$11.29	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$104,997
D2010	Plumbing Fixtures	\$7.89	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$73,377
D2020	Domestic Water Distribution	\$0.93	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$8,649
D2030	Sanitary Waste	\$2.11	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$19,623
D2040	Rain Water Drainage	\$0.57	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$5,301
D3010	Energy Supply	\$0.67	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$6,231
D3040	Distribution Systems	\$13.22	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$122,946
D3050	Terminal & Package Units	\$33.46	S.F.	9,300	15	2020	2035		106.67%	0.00%	16			\$311,178
D3060	Controls & Instrumentation	\$1.32	S.F.	9,300	15	2020	2035		106.67%	0.00%	16			\$12,276
D3090	Other HVAC Systems/Equip	\$3.93	S.F.	9,300	15	2020	2035		106.67%	0.00%	16			\$36,549
D4010	Sprinklers	\$5.08	S.F.	9,300	30	2020	2050		103.33%	0.00%	31			\$47,244
D4030	Fire Protection Specialties	\$0.10	S.F.	9,300	15	2020	2035		106.67%	0.00%	16			\$930
D4090	Other Fire Protection Systems	\$0.75	S.F.	9,300	15	2020	2035		106.67%	0.00%	16			\$6,975
D5010	Electrical Service/Distribution	\$2.81	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$26,133
D5020	Branch Wiring	\$5.64	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$52,452
D5020	Lighting	\$6.92	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$64,356
D5030810	Security & Detection Systems	\$1.90	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$17,670
D5030910	Fire Alarm Systems	\$3.43	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$31,899
D5030920	Data Communication	\$4.45	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$41,385
D5090	Other Electrical Systems	\$0.00	S.F.		15				0.00%	0.00%				\$0
E1090	Other Equipment	\$15.55	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$144,615
E2010	Fixed Furnishings	\$4.27	S.F.	9,300	20	2020	2040		105.00%	0.00%	21			\$39,711
Total									104.12%					\$2,069,125

System Notes

The facility description in the executive summary contains an overview of each system. The system notes listed below provide additional information on select systems found within the facility.

No data found for this asset

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the System Listing table. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
Total:		\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010230 - Paint & Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010901 - Wainscot - FRP	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 2020 Bldg

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
C3020420 - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020903 - VCT	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3010 - Energy Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4030 - Fire Protection Specialties	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4090 - Other Fire Protection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 2020 Bldg

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasted capital renewal (sustainment) requirements over the next ten years.




Condition Index Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation

Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 0%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2020	\$0	\$42,624.00	-2.00%	\$85,248.00	-4.00%
2021	\$0	\$43,903.00	-4.00%	\$87,805.00	-8.00%
2022	\$0	\$45,220.00	-6.00%	\$90,440.00	-12.00%
2023	\$0	\$46,576.00	-8.00%	\$93,153.00	-16.00%
2024	\$0	\$47,974.00	-10.00%	\$95,947.00	-20.00%
2025	\$0	\$49,413.00	-12.00%	\$98,826.00	-24.00%
2026	\$0	\$50,895.00	-14.00%	\$101,791.00	-28.00%
2027	\$0	\$52,422.00	-16.00%	\$104,844.00	-32.00%
2028	\$0	\$53,995.00	-18.00%	\$107,990.00	-36.00%
2029	\$0	\$55,615.00	-20.00%	\$111,229.00	-40.00%
Total:	\$0	\$488,637.00		\$977,273.00	

Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

The condition of a Campus is the accumulation of the condition evaluations of the component buildings and the site. Building condition is evaluated based on the functional systems and elements of a building and organized according to the **UNIFORMAT II Elemental Classification**. eCOMET uses parametric estimating methodology whereby historical costs for systems, components and equipment are collected by entities such as RSMeans and converted to unit costs, typically \$/SF, and used to approximate future construction costs or replacement values. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Current Replacement Value (CRV)** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:

Gross Area (SF): 135,080

Year Built: 1950

Last Renovation:

Replacement Value: \$3,563,409

Repair Cost: \$665,301

Total FCI: 18.67%

Total RSLI: 37.21%

FCA Score: 81.33



Description:


The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:		Gross Area:	135,080
Year Built:	1950	Last Renovation:	
Repair Cost:	\$665,301	Replacement Value:	\$3,563,409
FCI:	18.67%	RSLI%:	37.21%


Deficiency By Category




Deficiency By Priority



Deficiency By System



10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	42.71%	1.59%	\$32,315.84
G30 - Site Mechanical Utilities	58.00%	0.00%	\$0.00
G40 - Site Electrical Utilities	11.23%	68.81%	\$632,985.00
Totals:	37.21%	18.67%	\$665,300.84

Photo Album

The photo album consists of the various cardinal compass directions of the building..



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment)
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system as new construction.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$2.37	S.F.	135,080	35	1998	2033		40.00%	0.00%	14			\$320,140
G2020	Parking Lots	\$8.00	S.F.	135,080	35	1998	2033		40.00%	2.00%	14		\$21,645.43	\$1,080,640
G2030	Pedestrian Paving	\$2.33	S.F.	135,080	35	1998	2033		40.00%	0.00%	14			\$314,736
G2040105	Fence & Guardrails	\$1.15	S.F.	135,080	30	2019	2049		100.00%	6.87%	30		\$10,670.41	\$155,342
G2050	Landscaping	\$1.18	S.F.	135,080	25	1998	2023		16.00%	0.00%	4			\$159,394
G3010	Water Supply	\$1.09	S.F.	135,080	50	1998	2048		58.00%	0.00%	29			\$147,237
G3020	Sanitary Sewer	\$2.20	S.F.	135,080	50	1998	2048		58.00%	0.00%	29			\$297,176
G3030	Storm Sewer	\$1.25	S.F.	135,080	50	1998	2048		58.00%	0.00%	29			\$168,850
G4010	Electrical Distribution	\$2.55	S.F.	135,080	30	1998	2028		30.00%	0.00%	9			\$344,454
G4020	Site Lighting	\$2.98	S.F.	135,080	30	1980	2010		0.00%	110.00%	-9		\$442,792.00	\$402,538
G4030	Site Communication and Security	\$1.28	S.F.	135,080	30	1980	2010		0.00%	110.00%	-9		\$190,193.00	\$172,902
Total									37.21%	18.67%			\$665,300.84	\$3,563,409

System Notes

The facility description in the executive summary contains an overview of each system. The system notes listed below provide additional information on select systems found within the facility.

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

School Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

School Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G4010 - Electrical Distribution



Note:

School Assessment Report - Site

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communication and Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the System Listing table. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	Total
Total:	\$665,301	\$0	\$0	\$0	\$197,340	\$0	\$0	\$0	\$0	\$494,377	\$0	\$1,357,018
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$21,645	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,645
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$10,670	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$10,670
G2050 - Landscaping	\$0	\$0	\$0	\$0	\$197,340	\$0	\$0	\$0	\$0	\$0	\$0	\$197,340
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$494,377	\$0	\$494,377
G4020 - Site Lighting	\$442,792	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$442,792
G4030 - Site Communication and Security	\$190,193	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$190,193

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasted capital renewal (sustainment) requirements over the next ten years.




Condition Index Forecast by Investment Scenario

The chart below illustrates the effect of various investment levels on the building FCI for the next 10 years. The levels of investment shown below include:

- Current FCI: a variable investment amount based on renewing expired systems to maintain the current FCI for the building
- 2% Investment: an annual investment of 2% of the replacement value of the building, escalated for inflation
- 4% Investment: an annual investment of 4% of the replacement value of the building, escalated for inflation


Facility Investment vs. FCI Forecast



Year	Investment Amount Current FCI - 18.67%	2% Investment		4% Investment	
		Amount	FCI	Amount	FCI
2020	\$0	\$73,406.00	16.67%	\$146,812.00	14.67%
2021	\$0	\$75,608.00	14.67%	\$151,217.00	10.67%
2022	\$0	\$77,877.00	12.67%	\$155,753.00	6.67%
2023	\$197,340	\$80,213.00	15.59%	\$160,426.00	7.59%
2024	\$0	\$82,619.00	13.59%	\$165,239.00	3.59%
2025	\$0	\$85,098.00	11.59%	\$170,196.00	-0.41%
2026	\$0	\$87,651.00	9.59%	\$175,302.00	-4.41%
2027	\$0	\$90,280.00	7.59%	\$180,561.00	-8.41%
2028	\$494,377	\$92,989.00	16.22%	\$185,978.00	-1.78%
2029	\$0	\$95,778.00	14.22%	\$191,557.00	-5.78%
Total:	\$691,717	\$841,519.00		\$1,683,041.00	

Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$665,300.84

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$665,300.84


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Critical Immediate Need	2 - Trending Critical (Year 1)	3 - Necessary (Years 2-5)	4 - Recommended (Years 6-10)	5 - Grandfathered Project triggered	Total
G2020	Parking Lots	\$0.00	\$0.00	\$21,645.43	\$0.00	\$0.00	\$21,645.43
G2040105	Fence & Guardrails	\$0.00	\$0.00	\$0.00	\$10,670.41	\$0.00	\$10,670.41
G4020	Site Lighting	\$0.00	\$0.00	\$442,792.00	\$0.00	\$0.00	\$442,792.00
G4030	Site Communication and Security	\$0.00	\$0.00	\$190,193.00	\$0.00	\$0.00	\$190,193.00
	Total:	\$0.00	\$0.00	\$654,630.43	\$10,670.41	\$0.00	\$665,300.84

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary (Years 2-5):

System: G2020 - Parking Lots



Location: Site
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Resurface asphalt paving and restripe.
Qty: 9,400.00
Unit of Measure: S.Y.
Estimate: \$21,645.43
Assessor Name: Hayden Collins
Date Created: 10/30/2014

Notes: The parking lot adjacent to the building is beyond its service life, damaged and not ADA compliant, and should be resurfaced and modified for compliance with ADA standards, including a marked path of ingress to the main entrance.

System: G4020 - Site Lighting



Location: Site
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 135,080.00
Unit of Measure: S.F.
Estimate: \$442,792.00
Assessor Name: Hayden Collins
Date Created: 02/22/2020

Notes:

The existing site lighting system consists of a building mounted lighting program support by a few pole-mounted lights. Additional lighting is recommended.

System: G4030 - Site Communication and Security



Location: Site
Distress: Inadequate
Category: Mission Integrity
Priority: 3 - Necessary (Years 2-5)
Correction: Renew System
Qty: 135,080.00
Unit of Measure: S.F.
Estimate: \$190,193.00
Assessor Name: Hayden Collins
Date Created: 10/17/2014

Notes: This facilities security and alarm system is operation and has been upgraded over the past years. This project provides a budgetary consideration to improve the facilities security and alarm system.

Priority 4 - Recommended (Years 6-10):

System: G2040105 - Fence & Guardrails



Location: Loading dock
Distress: Inadequate
Category: Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Build secure trash dumpster enclosure
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$10,670.41
Assessor Name: Hayden Collins
Date Created: 01/21/2020

Notes: The trash dumpster is in the parking lot open to the public. The exterior services are not protected. Upgrades to include a protective dumpster enclosure is recommended.

Glossary

Abandoned	A facility owned by the city that is not occupied and not maintained. See Vacant.
Additional Cost	Total project cost is composed of hard and soft costs. Additional costs or soft expenses are costs that are necessary to accomplish the corrective work but are not directly attributable to the deficient systems direct construction cost, which are often referred to as hard cost. The components included in the soft costs vary by owner but usually include architect and contractor fees, contingencies and other owner-incurred costs necessary to fully develop and build a facility. These soft cost factors can be adjusted anytime within the eCOMET database at the owner's discretion.
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems, reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ASTM	ASTM International (ASTM): Originally known as the American Society for Testing and Materials, ASTM is an international standards organization that develops and publishes voluntary consensus technical standards for a wide range of materials, products, systems, and services.
BOMA	Building Owners Managers of America (BOMA): National organization of public and private facility owners focused on building management tools and maintenance techniques. eCOMET® reference: Building and component system effective economic life expectancies.
Building	A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior.
Building Addition	An area, space or component of a building added to a building after the original building's year built date. NOTE: As a convention in the database, "Main" was used to designate the original building. Additions built prior to 1987 (30 years) were included in the main building area calculations to reflect their predicted system depreciation characteristics and remaining service life.
Building Systems	eCOMET® uses UNIFORMAT II to organize building data. UNIFORMAT II was originally developed by the federal General Services Administration to delineate building costs by systems rather than by material. UNIFORMAT II was formalized by an NIST standard, NISTIR 6389 in 1999. It has been further quantified and updated by ASTM standard 2005, E1557-05. The Construction Specifications Institute, CSI, has taken over the standard as part of their MasterFormat / MasterSpec system.
Calculated Next Renewal	The year a system or building element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal refers to the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life. It is not normally included in an annual operating/maintenance budget. See calculated next renewal and next renewal.
City Cost Index (CCI)	RS Means provides building system, equipment, and construction costs at a national level. The City Cost Index (also provided by RS Means) localizes those costs to a geographic region of the United States. In eCOMET®, each building or site is assigned a City Cost Index, which adjusts all of the associated costs for systems, deficiencies and inventory to the local value.
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
Condition Budget	The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work.

School Assessment Report - Turner MS (KIPP Atlanta Collegiate)

Condition Index (CI) %	The Condition Index (CI) also known as the Remaining Service Life Index (RSLI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude soft cost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).
Correction	Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a UNIFORMAT II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction.
Cost Model	A cost model is a list of facility systems which could represent the installed systems a given facility. Included in the cost model are standard unit cost estimates, gross areas, life cycles and installed dates. Also represented is the repair cost for deficient systems, replacement values. See eCOMET® cost models.
Criteria	Criteria refer to the set of requirements, guidelines or standards that are assessed and rated to develop a score.
Current Period	The Current Period is the current year plus a user defined number of forward years.
Current Replacement Value (CRV)	The Current Replacement Value (CRV) of a facility, building or system represents the hypothetical cost of rebuilding or replacing an existing facility under today's codes and construction standards, using its current configuration. It is calculated by multiplying the gross area of the facility by a square foot cost developed in that facility's cost model. Replacement cost includes construction costs and owner's additional or soft costs for fees, permits and other expenses to reflect a total project cost.
Deferred Maintenance	Deferred maintenance is condition work deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose.
Deficiency Category	Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions include, but are not limited to: Accessibility Code Compliance, Appearance, Building Code Compliance, Deferred Maintenance, Energy, Environmental, Life Safety Code Compliance, and Safety.
Deficiency Priority	Priority refers to a deficiency's urgency for repair as determined by the assessment team. Five typical industry priority settings were used for the assessment: Priority 1 – Currently Critical; Priority 2 – Potentially Critical; Priority 3 – Necessary/Not Yet Critical; Priority 4 – Recommended.
Distress	Distress refers to a user-defined root cause of a deficiency. Distress descriptions are: Beyond Service Life, Damaged, Inadequate, Needs Remediation, and Missing.
eCOMET®	Energy and Condition Management Estimation Technology (eCOMET®) is Parsons proprietary facility asset management software developed to provide facility managers with a state of the art, web-based tool to develop and maintain a comprehensive database of FCA data and information used for facility asset management, maintenance and repair, and capital renewal planning. eCOMET® is used by Parsons and its clients as the primary tool for collecting FCA data, preparing cost estimates, generating individual facility reports and cost estimates, and developing the overall capital renewal program.
eCOMET® Cost Models	eCOMET cost models are derived from RS Means Square Foot Cost Data cost models and these models are used to develop the current replacement value (CRV) and assign life cycle costs to the various systems within a building. Cost models are assigned current costs-per-square-foot to establish replacement values. The Cost models are designed to represent a client specific facility that meets local standards cost trends.

School Assessment Report - Turner MS (KIPP Atlanta Collegiate)

Element	Elements are the major components that comprise building systems as defined by UNIFORMAT II.
Expected Life	Also referred to as Useful Life. See Useful Life definition.
Facility	A facility refers to site(s) building(s) or building addition(s) or combinations thereof that provide a particular service.
Facility Attributes	Customizable eCOMET fields to identify attributes specific to a facility. These fields are part of the eCOMET database set-up with the owner.
Facility Condition Assessment (FCA)	A facility condition assessment (FCA) is a visual inspection of buildings and grounds at a facility to identify and estimate current and future needed repairs or replacements of major systems for planning and budgeting purposes. It is typically performed for organizations that are tasked with the day to day maintenance, operation, and capital renewal (replacement) of building systems and components of a large inventory of facilities. The primary goal of an FCA is to objectively and quantifiably identify, inspect, and prioritize the repair and replacement needs of the building and ground systems (e.g., roofs, windows, doors, floor finishes, plumbing fixtures, parking lot, and sidewalks) within facilities that have either failed or have surpassed their service life, and to identify and forecast future capital replacement needs for systems that have not yet failed, but planned replacement of those systems is needed to ensure that the facilities will continue to meet the mission of the organization.
Facility Condition Index (FCI%)	FCI is an industry-standard measurement of a facility's condition that is the ratio of the cost to correct a facility's deficiencies to the Current Replacement Value of the facilities. The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.
Forecast Period	The Forecast Period refers to a user defined number of years forward of the Current Period.
Gen (Generate)	The Cost Model has a Gen box for each system line item. By checking the box, eCOMET will generate life cycle deficiencies based on the Year Installed and the Life for that system. Systems that typically do not re-generate (foundations, floor construction, roof construction, basement walls, etc.) would not have the Gen box checked as those systems would not re-generate at the end of a life cycle. In those instances, it would be more practical and cost effective to demolish the entire facility than re-new those systems.
Gross Square Feet (GSF)	The size of the enclosed floor space of a building in square feet measured to the outside face of the enclosing wall.
Life Cycle	Life cycle refers to the period of time that a building or site system or element can be expected to adequately serve its intended function. Parsons assigns expected life cycles to all building systems based on Building Operators and Managers of America (BOMA) recommended life cycles, manufacturers suggested life, and RS Means cost data, and client-provided historical data. BOMA standards are a nationally recognized source of life cycle data for various components and/or systems associated with facilities. RS Means is a national company specializing in construction estimating and costs.
Next Renewal	Next Renewal refers to a manually-adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately reflect current conditions.
Order of Magnitude	Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.
Remaining Service Life (RSL)	RSL is the number of years service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the 'Calculated Next Renewal' date or the 'Next Renewal' date whichever one is the later date.

School Assessment Report - Turner MS (KIPP Atlanta Collegiate)

Remaining Service Life Index (RSLI)	The Remaining Service Life Index (RSLI), also known as the Condition Index (CI), is calculated as the sum of a renewable system's or component's Remaining Service Life (RSL) Value divided by the sum of a system's or component's Replacement Value (both values exclude softcost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining service life).
Remaining Service Life Value	Remaining Service Life Value, also known as the RSL Weight, is a calculated value used to determine the RSLI and is equal to the system Value (Unit Cost * Qty) * RSL (not displayed).
Renewal Factors	Renewal factors represent the difference in cost of renovating or replacing an existing system, rather than new construction of a building system. For example, installing a new built-up roof on an existing building would include removing and disposing of the old roof, a cost not associated with new construction. Using a renewal premium to account for demolition and other difficulty costs, Parsons typically assigns a renewal factor of 110%.
Renewal Schedule	A timeline that provides the items that need repair the year in which the repair is needed and the estimated price of the renewal.
Repair Cost	Repair cost is the sum of all the deficiencies associated with a building or multiple buildings/facilities. It will include any applied soft costs or City Cost Indexes.
Replacement Value	See Current Replacement Value.
Site	A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.
Soft Costs	Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user-defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses.
Sustainability	Sustainability refers to the collection of policies and strategies that meet society's present needs without compromising the ability of future generations to meet their own needs.
System	System refers to building and related site work elements as described by ASTM Uniformat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.
System Generated Deficiency	eCOMET automatically generates system deficiencies based on system life cycles using the systems installation dates as the base year. By adjusting the Next Renewal date ahead or behind the predicted or stated life cycle date, a system cost will come due earlier or later than the originally installed life cycle date. This utility accounts for good maintenance conditions and a longer life, or early expiration of a system life due to any number of adverse factors such as poor installation, acts of god, material defects, poor design applications and other factors that may shorten the life of a material or system. It is important to mention that the condition of the systems is not necessarily a reflection of maintenance practices, but a combination of system usage and age.
UNIFORMAT	ASTM UNIFORMAT II, Classification for Building Elements (E1557-97), a publication of the Construction Specification Institute (CSI), is a format used to classify major facility components common to most buildings. The format is based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies.
Unit Price	The Unit Price (Raw) x the Additional Cost Template percentage.
Unit Price (Raw)	The actual \$/sq. ft. cost being used for the building and systems. It will include adjustments for the City Cost Index applied to the facility.

Useful Life	Also known as Expected Life, Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in the database are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from client- defined historical experience.
Vacant	Vacant refers to a facility that is not occupied but is a maintained facility. See Abandoned.
Year Built	The year that a building or addition was originally built based on substantial completion or occupancy.
Year Installed	The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.



Suitability Report - Full

Project #: 12382	County: Atlanta Public Schools	Site #: 0191
Project: APS Assessments 2019	Region: 761	Site: Turner MS
Grade Config: 9-12	Site Type: Charter	Site Size: 10.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Unsat	0.00	1.50	0.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Excel	9.75	9.75	100.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Poor	0.41	0.82	50.00
Size	Fair	1.33	2.05	65.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Fair	0.40	0.61	65.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Excel	2.39	2.39	100.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Poor	0.37	0.74	50.00
Size	Good	1.47	1.84	80.00
Location	Poor	0.28	0.55	50.00
Storage/Fixed Equip	Unsat	0.00	0.55	0.00
Art				
Environment	Excel	0.65	0.65	100.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Unsat	0.00	1.35	0.00

Project #: 12382

County: Atlanta Public Schools

Site #: 0191

Project: APS Assessments 2019

Region: 761

Site: Turner MS

Grade Config: 9-12

Site Type: Charter

Site Size: 10.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	3.37	0.00
Location	Unsat	0.00	1.01	0.00
Storage/Fixed Equip	Unsat	0.00	1.01	0.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Poor	3.00	6.00	50.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Unsat	0.00	0.42	0.00
Size	Excel	1.05	1.05	100.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
Media Center				
Environment	Fair	0.60	0.93	65.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Unsat	0.00	0.70	0.00
Restrooms (Student)	Fair	0.60	0.93	65.00
Administration	Excel	2.10	2.10	100.00
Counseling	Good	0.34	0.42	80.00
Clinic	Excel	0.34	0.34	100.00
Staff WkRm/Toilets	Excel	0.91	0.91	100.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Unsat	0.00	4.00	0.00
Pedestrian Traffic	Unsat	0.00	0.43	0.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Unsat	0.00	1.05	0.00
Safety and Security				
Fencing	Excel	0.78	0.78	100.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Poor	0.25	0.50	50.00
Total For Site:		65.53	97.27	67.37

Comments

Project #: 12382

County: Atlanta Public Schools

Site #: 0191

Project: APS Assessments 2019

Region: 761

Site: Turner MS

Grade Config: 9-12

Site Type: Charter

Site Size: 10.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Turner Middle School is home to KIPP Collegiate charter school for students in grades 9-12. KIPP is an "AP for All" school. This is a three story facility with a separate building for the gym and band programs. There is construction includes a new cafeteria, classrooms, and a black box theatre. All classrooms serve multiple purposes and teachers float to multiple rooms throughout the day.				
Suitability - MS->Learning Environment-->Interior Environment				
This building is narrow and crowded. The HVAC system is inadequate in classrooms and in hallways. The acoustics are loud in most spaces. Lighting varies by room. Air circulation is minimal, with heavy air in the dance room, science rooms, restrooms and the cafeteria.				
Suitability - MS->Learning Environment-->Exterior Environment				
There are no external learning spaces at this school.				
Suitability - MS->General Classrooms-->Environment				
This building is narrow and crowded. In classrooms and in hallways. The acoustics are loud in most spaces. Lighting varies by room. Air circulation is minimal, with heavy air in many rooms.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
Storage in all classrooms is minimal. Some classrooms have no storage. Storage spaces exist for teachers in other parts of the building.				
Suitability - MS->Instructional Resource Rooms-->Environment				
This building is narrow and crowded. In classrooms and in hallways. The acoustics are loud in most spaces. Lighting varies by room. Air circulation is minimal, with heavy air in many rooms.				
Suitability - MS->Instructional Resource Rooms-->Size				
The resource room meets 78% of the standard.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip				
This smaller room has little fixed storage.				
Suitability - MS->Science-->Storage/Fixed Equip				
There are six science classrooms in the building. One of these has been remodeled to have lab space for all students, with sinks at each work space, a chemical shower/hood, and safety equipment. The other five science classes have two sinks in each, but no chemical shower or separate lab space with water and gas. These other rooms also lack a prep room.				
Suitability - MS->Music-->Environment				
The choir room is located in a room designed for storage. Risers were built to fit the space. It is loud with no acoustical padding or other additions to enhance sound. The space is cramped. Students can touch the ceiling from the top riser. There is no natural light in the band room.				
Suitability - MS->Music-->Location				
The choir room is located next to the computer lab, which is often used for testing. The band is in a separate building which competes for sound with the gym.				
Suitability - MS->Music-->Storage/Fixed Equip				
There is no fixed equipment for this program. There are no practice rooms or office spaces. The rooms do not have drinking fountains.				
Suitability - MS->Career Tech Ed-->Environment				
There is no CTAE space available in this building.				
Suitability - MS->Career Tech Ed-->Size				
There is no CTAE space available in this building.				

Project #: 12382

County: Atlanta Public Schools

Site #: 0191

Project: APS Assessments 2019

Region: 761

Site: Turner MS

Grade Config: 9-12

Site Type: Charter

Site Size: 10.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Career Tech Ed-->Location				
There is no CTAE space available in this building.				
Suitability - MS->Career Tech Ed-->Storage/Fixed Equip				
There is no CTAE space available in this building.				
Suitability - MS->P.E.-->Size				
The weight room is 62% of the standard. The gym is 36% of the standard. The school has two gyms in the original design. One is a multipurpose room with hard wood floors, housing a stage and overflow from the cafeteria. The other is a separate building designed for athletic practice and competition.				
Suitability - MS->Performing Arts-->Environment				
This space was designed as a gym. It is used for cafeteria overflow. The constant moving of students in and out of this space do not make it conducive to learning. There is poor lighting in this space, both natural and electric. Classes for the performing arts program are held on the stage, not in a separate classroom. The dance class is held in a separate room that was designed as storage. It is hot and muggy in the dance room with no air circulation.				
Suitability - MS->Media Center-->Environment				
There is little natural light in this space. The media center is used as office space for staff. It is open with little storage or shelving space available.				
Suitability - MS->Media Center-->Storage/Fixed Equip				
There is no storage or fixed equipment in this space.				
Suitability - MS->Restrooms (Student)				
More student restrooms are necessary to serve this number of students. Urinals are not have privacy partitions.				
Suitability - MS->Counseling				
Counselors have offices in the co-working space of the media center. This space is connected to the front office space.				
Suitability - MS->Clinic				
The office designed to be the nurses clinic is used by the assistant principal. The clinic is in a smaller space that does not meet all requirement because of size, number of beds, cold storage and locked files. However the actual nurses clinic meets all requirements.				
Suitability - MS->Outside-->Vehicular Traffic				
Buses and cars are not separated. Cars do a U turn in the drop off lane because there is no natural exit. This process is further obstructed by the construction on the campus.				
Suitability - MS->Outside-->Pedestrian Traffic				
There are few sidewalks on the school property. Students walk through parking lots to access play fields. Sidewalks are under construction in the neighborhood. Sixty to seventy percent of the students commute using the Atlanta mass transit system, Marta. These students walk a half mile to the Marta stop without sidewalks for much of the walk.				
Suitability - MS->Outside-->Athletic Courts and Fields				
Although there is a new football field with track adjacent to the school's parking lot, this belongs to the city parks department. No other athletic fields exist.				
Suitability - MS->Safety and Security-->Signage & Way Finding				
A few signs are missing from the building, including: Under Surveillance and Subject to Search. Visitor parking is not marked.				
Suitability - MS->Safety and Security-->Ease of Supervision				
The multiple levels and buildings on this campus impede supervision. There are a number of hiding areas and camera blind spots both inside and outside the building.				

Project #:	12382	County:	Atlanta Public Schools	Site #:	0191
Project:	APS Assessments 2019	Region:	761	Site:	Turner MS
Grade Config:	9-12	Site Type:	Charter	Site Size:	10.00

Suitability	Rating	Score	Possible Score	Percent Score
-------------	--------	-------	----------------	---------------

Suitability - MS->Safety and Security-->Controlled Entrances

There is no security vestibule. It is difficult to determine where the main entrance is, and visitors are let in alternate doors.