

Ongoing Activities

7/30/18 – 8/3/18

- Site clearing & grubbing in progress
- Tree removal at Boys & Girls Club ongoing
- Silt fence installation ongoing
- Richland loop demolition ongoing
- Boys & Girls Club abatement complete (by APS)
- RTU refrigerant removal at Boys & Girls Club
- Site utilities installation commencing

Upcoming Activities

- Boys & Girls Club utility disconnect & building demolition
- Erosion control at east side of Boys & Girls Club
- Underground detention system installation
- Continuing installation of site utilities

Overview



View of Project Site (From West Side of Boys & Girls Club)

Safety Sector



Slips, Trips, & Falls

In the midst of rainy weather, safety concerns for all workers and visitors onsite are slips, trips, and falls. The project site can become muddy and it is important to be aware of your surroundings and wear proper footwear to navigate the site. Similar to when you're driving, it's important to not be distracted by texts or calls while walking through the site.



Tree and Debris Removal at East Side



Tree Save Fence Installation at East Side



Precast Manhole Structures Delivery