



**Week Ending 10/27/18** 

#### **COMPLETED ACTIVITIES:**

- Demolition of 5th Grade Pod
- Framing of 5<sup>th</sup> Grade Pod Walls
- Electrical Wall Rough-In in 5<sup>th</sup> Grade Pod
- Installation of Interior Storefronts in 5<sup>th</sup> Grade Pod
- Overhead MEP Rough-In in 5<sup>th</sup> Grade Pod
- Demolition of 2<sup>nd</sup> Floor Cafeteria Ceilings
- Overhead MEP Rough-In in 2nd Floor Cafeteria
- Demolition of 2<sup>rd</sup> Floor Kitchen Ceilings
- Installation of 2<sup>nd</sup> Floor Kitchen Acoustical Ceiling Tile
- Painting of 2<sup>nd</sup> Floor Kitchen
- Demolition of 3<sup>rd</sup> Floor Classroom Ceilings
- Painting of 3<sup>rd</sup> Floor Classrooms
- Interior Courtyard Curtainwall Painting on the 1st Floor
- Water Source Heat Pump Power Distribution for Phase 1A
- Hanging and Finishing Drywall in 5th Grade Pod
- Installation of 3<sup>rd</sup> Floor Classroom Acoustical Ceiling Tile
- Furring out of 3<sup>rd</sup> Floor Corridor Walls
- Demolition of 3<sup>rd</sup> Floor Classroom Flooring
- Interior Courtyard Curtainwall Painting on 3rd Floor
- Sawcut Slab for Curtain Wall Shear Walls on 2<sup>nd</sup> Floor
- Installation of Light Fixtures in 2<sup>nd</sup> Floor Cafeteria and East Corridor
- Framing 2<sup>nd</sup> floor Cafeteria and East Corridor Ceilings
- Installing 2<sup>nd</sup> Floor Cafeteria and East Corridor Ceiling Tile
- Installing 3<sup>rd</sup> Floor Corridor Ceiling Tile
- Installation of 3<sup>rd</sup> Floor Corridor Flooring





- Installing 3<sup>rd</sup> Floor Classroom Flooring
- Demolition of 5th Grade Flooring
- Painting 5<sup>th</sup> Grade Walls
- Frame 5<sup>th</sup> Grade Ceilings
- Install 5th Grade Ceiling Tile
- Painting of 3<sup>rd</sup> Floor Corridors
- Installing Flooring in 3<sup>rd</sup> Grade Classrooms
- Demolition of Cafeteria flooring
- Mechanical/Electrical Final Inspections
- Final Cleaning in the Kitchen
- Installing 5th Grade Flooring
- Final Cleaning in 5th grade pod
- Final Cleaning in Cafeteria
- Final Cleaning in 3<sup>rd</sup> Floor Corridor
- HVAC Equipment Startup
- Low Voltage Rough-In for Phase 1A
- Installing Rebar in the Shear Wall Foundation
- Building Final Inspection
- Wall and Ceiling Demo (Phase 1B)
- Metal Stud Framing (Phase 1B)
- In Wall Rough-In for Phase 1B
- Begin One Siding Walls for Phase 1B
- Installation of the Cooler/Freezer Condensers (Phase 1A)
- Pour Footings for Shear Wall
- Pouring 2<sup>nd</sup> floor shear walls
- Install duct and piping in band area





- In wall rough in (band area)
- In wall inspection for band area
- Installed rebar for 3<sup>rd</sup> floor shear wall
- Electrical wall rough in (8th grade pod)
- Installing ductwork, piping for 8th grade pod
- Electrical wall rough in for auditorium
- Demo trees
- Demo sidewalk in front of the building
- Electrical wall rough in for 3<sup>rd</sup> floor office and pre-K
- Installing ductwork and piping in the auditorium area
- Constructing the ceiling grid mock-up
- Installing ductwork and piping office/pre-k pod
- Installing electrical wall rough in 1st grade pod
- Installing door frames on 2<sup>nd</sup> floor 8<sup>th</sup> grade pod
- Electrical Wall Rough In 4th Grade Pod
- In Wall Inspection 1st grade Pod
- Installing ductwork and piping Kindergarten Pod
- Insulating ductwork and piping Kindergarten Pod/Pre-K/Office
- Demo Flooring Parent Center Area
- Install Ductwork and Piping 1st Grade Pod
- Hanging and finishing drywall in band area
- Hanging and finishing drywall in 8th grade pod
- Ductwork, piping, and fire dampers 4th grade pod
- Insulating ductwork and piping 4<sup>th</sup> grade pod
- Installing ceiling grid band area
- Low voltage rough in band area





**Week Ending 10/27/18** 

- Hanging and finishing drywall 3<sup>rd</sup> floor office/pre-k
- Installing steel channels for curtainwall
- Pouring footings for the knee walls
- Demo curtainwall openings
- Framing 2<sup>nd</sup> Hanging and finishing drywall kindergarten pod/1<sup>st</sup> grade pod
- floor corridor ceilings
- Installing ceiling grid in the 3<sup>rd</sup> floor office/pre-k area
- Pouring knee walls
- Installing lights and devices in band area/8<sup>th</sup> grade pod
- Underground plumbing

#### • CURRENT ACTIVITIES:


- Metal stud framing and sheathing for the curtain walls
- Installing ceiling tile on 2<sup>nd</sup> floor
- Installing low voltage in 3<sup>rd</sup> grade pod
- Installing water source heat pumps on 2<sup>nd</sup> floor
- Installing curtainwall framing
- 2<sup>nd</sup> floor electrical overhead inspection
- Installing lights and devices 3<sup>rd</sup> floor office/pre-k
- Hanging and finishing drywall 3<sup>rd</sup> floor kindergarten





**Week Ending 10/27/18** 

#### **PROGRESS PHOTOS:**

































**Week Ending 10/27/18** 

#### SCHEDULE:

• Substantial Completion Date: July 31, 2019

· Schedule Status: On Schedule

#### **BUDGET:**

• Construction Budget: \$8,400,000

• Billed to Date: \$2,819,170.00 (Through 9/30/2018)