

Harper Archer Elementary School Weekly Construction Report

June 15, 2018



Picture 1: Demolition to create the new media center



Picture 2: Relocated dust walls in Area A and C



Picture 3: Demolition in Area A



Picture 4: Concrete patching for existing chases

Harper Archer Elementary School Weekly Construction Report

June 15, 2018




Picture 5: Framing in Area B in progress



Picture 6: Electrical in wall rough-in on going



Picture 7: New door openings in Area B




Picture 8: Framing in temporary nurse's clinic

Harper Archer Elementary School

Weekly Construction Report

June 15, 2018



Ongoing:

Phase 1:

- Demolition in area A and C
- Framing of interior walls in Area B
- Concrete patching of existing mechanical chases in all areas
- MEP in wall rough in
- Bathroom plumbing rough-in in all areas.

Upcoming:

Phase 1:

- Masonry wall infills
- Framing inspection
- Plumbing inspection
- Door frame installation